

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size

Iyathis S
Christ Nagar Public School,
Valakkadu (Elamba P.O.)
Attingal, Edm. District

Basement - 290.40m² x 3.60m ht
G.F - 623.39m² x 3.60m ht
FF - 1096.90m² x 3.60m ht
SF - 1000.77m² x 3.60m ht
TF - 933.33m² x 3.60m ht
Att.F - 965.03m² x 3.60m ht
5th Floor - 972.04 x 3.60m ht

5. Period for which the certificate is issued

2020-21

6. Nature of defects, if any

Nil

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

7. Any Major Defects noticed which will render the building unsafe in any manner

Nil

8. Whether the structure is sound or not for conducting Classes

Sound for conducting classes under normal weather condition


Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 2/10/2020 and found to be fit/unfit to conduct classes for the period 2020-21 for the reasons stated above.

Place: Elamba

Date: 2/10/2020



Building Inspection Engineer

CHRIST NAGAR PUBLIC SCHOOL
VALAKKADU, ELAMBA P.O.
ATTINGAL, TRIVANDRUM - 695 103

MANAGER
CHRIST NAGAR PUBLIC SCHOOL
VALAKKADU, ELAMBA P.O.
ATTINGAL, TRIVANDRUM - 695 103